



VEKTEK, INC.  
 1334 E. SIXTH AVE.  
 P.O. BOX 625  
 EMPORIA, KS. 66801  
 U.S.A.

# PARTS LIST

PL-2166  
 REV. E ECN2734  
 PAGE 1 OF 1

ASSEMBLIES AFFECTED: 21-1215-04  
 21-1215-04F  
 CYL BB/MM/DA. 8800# x 1.5 STK.

DRAWN/DATE JACOB  
 050897

PISTON  
 82-0115-07

GLAND 82-0315-01  
 (RE-TORQUE TO  
 55 Ft.Lbs.)

BODY, (NON-  
 REPLACEMENT  
 PART)



\* O-RING (2)  
 39-0500-42 (Std.)  
 39-0510-25 (Flourocarbon)


\* WIPER  
 39-0110-19 (Std.)  
 39-0500-20 (Flourocarbon)

\* O-RING  
 39-0010-13 (Std.)  
 39-0120-14 (Flourocarbon)

\* ROD SEAL  
 39-0110-48 (Std.)  
 39-0120-07 (Flourocarbon)

\* PISTON SEAL  
 39-H110-31 (Std.)  
 39-V110-31 (Flourocarbon)

PLUG, METAL  
 30-6011-45



APPLY LUBRICANT TO ALL SEALS PRIOR TO INSTALLATION.  
 DO NOT USE SILICONE TYPE LUBRICANTS.

\* INCLUDED IN SEAL KIT NO. (Std.) 60-2102-01  
 (Flourocarbon) 6V-2102-01