



APPLY LUBRICANT TO ALL SEALS PRIOR TO INSTALLATION.
DO NOT USE SILICONE TYPE LUBRICANTS.

WARNING

DO NOT OVER TORQUE ADAPTER 30871123.
TORQUE IS NOT TO EXCEED 60 IN-LBS



ROTARY UNION
NOT FIELD SERVICEABLE



No.	QTY	PART No.	DESCRIPTION
1	4	30871123	ASSY, ADAPTER, RU, MM, SAE 2

PARTS LIST



VEKTEK, INC.
1334 E. SIXTH AVE. P.O. BOX 625
EMPORIA, KS. 66801 U.S.A.

ASSEMBLIES AFFECTED
32-4244-01

PARTS LIST, ASSY, RU, QP, SAE 4, BRZ

A	3383	RELEASE	JDW	12/14/17
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE

DRW BY: JDW
DATE: 12/14/17
DRAWING STATUS: **Released**
PRODUCTION APPROVED FOR RELEASED STATUS ONLY

SIZE
A
PL3208
REV
A

FORM FEG035_PL_ASIZE, REV. B