



VEKTEK, INC.
1334 E. SIXTH AVE.
P.O. BOX 625
EMPORIA, KS. 66801
U.S.A.

PARTS LIST

PL-7088


REV N
ECN 2503

ASSEMBLIES AFFECTED: 15281800
15281800F

DRAWN/DATE

ROMINE
09/29/00

ASSY, SC, LP, BF, 5000, DA, RH
UNIT WITH PLUNGER CLUTCH
MODELS THAT APPLY
15281800F , Revision E & Earlier
15281800F , Revision E & Earlier




* INCLUDED IN SEAL KIT No. (Std.) 60-7110-10
(Fluorocarbon) 6V-7110-10
** INCLUDED IN SPRING KIT No. 61-7040-02

ALSO AVAILABLE:
IS-1505-INSTRUCTION SHEET

APPLY LUBRICANT TO ALL SEALS
PRIOR TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.

ASSY, SC, LP, BF, 5000, DA, RH
UNIT WITHOUT PLUNGER CLUTCH
AS OF 11/09/04
MODELS THAT APPLY
15281800 , Revision F & Later
15281800F , Revision F & Later



* INCLUDED IN SEAL KIT No. (Std.) 60-7110-10
(Fluorocarbon) 6V-7110-10

ALSO AVAILABLE:
IS-1505-INSTRUCTION SHEET

APPLY LUBRICANT TO ALL SEALS
PRIOR TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.

