



VEKTEK, INC.
1334 E. SIXTH AVE.
P.O. BOX 625
EMPORIA, KS. 66801
U.S.A.


PARTS LIST

PL-7089
REV N
ECN2503
DRAWN/DATE
ROMINE
09/29/00

ASSEMBLIES AFFECTED: 15281801
15281801F

ASSY, SC, LP, BF, 5000, DA, LH

UNIT WITH PLUNGER CLUTCH
MODELS THAT APPLY
15281801 , Revision E & Earlier
15281801F , Revision E & Earlier




* INCLUDED IN SEAL KIT No. (Std.) 60-7110-10 (Fluorocarbon) 6V-7110-10
** INCLUDED IN SPRING KIT No. 61-7040-02

ALSO AVAILABLE:
IS-1505 INSTRUCTION SHEET

APPLY LUBRICANT TO ALL SEALS
PRIOR TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.

ASSY, SC, LP, BF, 5000, DA, LH

UNIT WITHOUT PLUNGER CLUTCH
AS OF 11/09/04
MODELS THAT APPLY
15281801 , Revision F & Later
15281801F , Revision F & Later



APPLY LUBRICANT TO ALL SEALS
PRIOR TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.

ALSO AVAILABLE:
IS-1505 INSTRUCTION SHEET

