



VEKTEK, INC.  
1334 E. SIXTH AVE.  
P.O. BOX 625  
EMPORIA, KS. 66801  
U.S.A.


# PARTS LIST

PL-7104  
REV. K  
ECN 2503  
DRAWN/DATE ROMINE  
08/06/01

ASSEMBLIES AFFECTED: 15062101  
15062101F

ASSY, SC, LP, TF, 7500, DA, LH

UNIT WITH PLUNGER CLUTCH  
MODELS THAT APPLY  
15062101 , Revision B & Earlier  
15062101F , Revision B & Earlier




APPLY LUBRICANT TO ALL SEALS PRIOR TO INSTALLATION.  
DO NOT USE SILICONE TYPE LUBRICANTS.  
FOR PROPER ARM MOUNTING SEE IS-1505

\*INCLUDED IN SEAL KIT (Std) 60-7110-12  
(Fluorocarbon) 6V-7110-11  
\*\* INCLUDED IN SPRING KIT 61-7040-07

ASSY, SC, LP, TF, 7500, DA, LH

UNIT WITHOUT PLUNGER CLUTCH  
AS OF 11/09/04  
MODELS THAT APPLY  
15062101 , Revision C & Later  
15062101F , Revision C & Later



APPLY LUBRICANT TO ALL SEALS PRIOR TO INSTALLATION.  
DO NOT USE SILICONE TYPE LUBRICANTS.  
FOR PROPER ARM MOUNTING SEE IS-1505

\* INCLUDED IN SEAL KIT (Std) 60-7110-12  
(Fluorocarbon) 6V-7110-11

