



VEKTEK, INC.  
1334 E. SIXTH AVE.  
P.O. BOX 625  
EMPORIA, KS. 66801  
U.S.A.

# PARTS LIST

PL-7107  
REV. L  
ECN 2503  
DRAWN/DATE ROMINE  
08/06/01

ASSEMBLIES AFFECTED: 15062104  
15062104F


ASSY, SC, LP, TF, 7500, DA, LH, LS

UNIT WITH PLUNGER CLUTCH

MODELS THAT APPLY

15062104 , Revision B & Earlier

15062104F , Revision B & Earlier



APPLY LUBRICANT TO ALL SEALS PRIOR TO INSTALLATION.  
DO NOT USE SILICONE TYPE LUBRICANTS.  
FOR PROPER ARM MOUNTING SEE IS-1505

\*INCLUDED IN SEAL KIT (Std) 60-7110-12  
(Fluorocarbon) 6V-7110-11  
\*\* INCLUDED IN SPRING KIT 61-7040-07

ASSY, SC, LP, TF, 7500, DA, LH, LS


UNIT WITHOUT PLUNGER CLUTCH

AS OF 11/09/04

MODELS THAT APPLY

15062104 , Revision C & Later

15062104F , Revision C & Later



APPLY LUBRICANT TO ALL SEALS PRIOR TO INSTALLATION.  
DO NOT USE SILICONE TYPE LUBRICANTS.  
FOR PROPER ARM MOUNTING SEE IS-1505

\*INCLUDED IN SEAL KIT (Std) 60-7110-12  
(Fluorocarbon) 6V-7110-11

