

1



2

LUBRICATE ALL SEALS WITH CLEAN HYDRAULIC OIL PRIOR TO ASSEMBLY.
DO NOT USE SILICONE BASED LUBRICANTS.



B


B



N/A	N/A	62708002	REPAIR KIT	NOTED
5	4	39010061	BU RING, (-010)	X
4	2	39000039	O-RING, (-014)	X
3	4	31050012	DIFFUSER, DISK, SAE 4	X
2	2	31050009	FILTER, DISC, SAE 4, 25 MICRON	X
1	2	23002017	RETAINING RING, INTERNAL, 10 MM	X
No.	QTY	PART No.	DESCRIPTION	Repair Kit

A

A

PARTS LIST	 VEKTEK VEKTEK, INC. 1334 E. SIXTH AVE. P.O. BOX 625 EMPORIA, KS. 66801 U.S.A.
	ASSEMBLIES AFFECTED 47-0842-02 L7-0842-02
SIZE A	MPLV7243
REV A	REV A

A	3538	RELEASE	JDW	07/17/18
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE
DRW BY: JDW	DRAWING STATUS: Released			
DATE: 07/17/18	PRODUCTION APPROVED FOR RELEASED STATUS ONLY			

1

2

FORM FEG035_PL_ASIZE, REV. B

SHEET 1 OF 1