



THIS IS A TWO PAGE PARTS LIST.  
 THIS FIRST PAGE APPLIES TO  
 MODEL 50-4085-00 AT REVISION C AND LATER REVISIONS.



APPLY LOW STRENGTH  
 THREAD LOCKER TO THREADS.  
 TIGHTEN TO 25 IN-LBS TORQUE.

M3 FITTING IS AVAILABLE  
 TO ORDER SEPARATELY  
 AND NOT PROVIDED  
 WITH THIS ASSEMBLY

| NO  | QTY | PART NO  | DESCRIPTION                                | REPAIR KIT |
|-----|-----|----------|--|------------|
| 1   | 2   | 21500055 | SCREW, CAP, BTNH, M3 X 4, SST, w/ BND WSHR | X          |
| 2   | 1   | 23350133 | SPRING, COMPRESSION                        | X          |
| 3   | 1   | 39051025 | O-RING, (-011)                             | X          |
| 4   | 1   | 85040002 | RETAINER, SENSOR, POSITION, PNEU           |            |
| 5   | 1   | 85040003 | PISTON, SENSOR, POSITION, PNEU, OCO        |            |
| 6   | 2   | 39V00053 | O-RING, (-007)                             | X          |
| 8   | N/A | P3001500 | TBG, 1/8, NATURAL COLOR                    |            |
| 9   | N/A | P3037020 | 1/8 TUBE - M3 CONNECTOR                    |            |
| N/A | N/A | 62504000 | KIT, REPAIR                                | NOTED      |
| N/A | N/A | 1S5003   | INSTRUCTION SHEET                          |            |

**PARTS LIST**



VEKTEK, INC.  
 1334 E. SIXTH AVE. P.O. BOX 625  
 EMPORIA, KS. 66801 U.S.A.

ASSEMBLIES AFFECTED  
 50-4085-00


PARTS LIST, ASSY, SENSOR, POSITION, PNEU, OCO

SIZE A PL5003


REV E

|         |                        |  |            |         |
|---------|------------------------|--|------------|---------|
| E       | 5164                   | RELEASE                                      | RLK        | 8/28/23 |
| REV     | IN ACCORDANCE WITH ECN | EFFECTIVE DATE                               | REVISED BY | DATE    |
| DRW BY: | JDW                    | <b>DRAWING STATUS: Released</b>              |            |         |
| DATE:   | 11/03/15               | PRODUCTION APPROVED FOR RELEASED STATUS ONLY |            |         |

THIS IS A TWO PAGE PARTS LIST.  
 THIS SECOND PAGE APPLIES TO  
 MODEL 50-4085-00 AT REVISION B AND EARLIER REVISIONS.



| NO  | QTY | PART NO  | DESCRIPTION                                 | REPAIR KIT |
|-----|-----|----------|---|------------|
| 1   | 2   | 21500055 | SCREW, CAP, BTNH, M3 X 4, SST, w/ BND WSHER | X          |
| 2   | 1   | 23350133 | SPRING, COMPRESSION                         | X          |
| 3   | 1   | 39051025 | O-RING, (-011)                              | X          |
| 4   | 1   | 85040002 | RETAINER, SENSOR, POSITION, PNEU            |            |
| 5   | 1   | 85040003 | PISTON, SENSOR, POSITION, PNEU, OCO         |            |
| 6   | 2   | 39V00053 | O-RING, (-007)                              | X          |
| 7   | 1   | 39V10029 | WIPER, PRESS-IN, (1/4)                      | X          |
| 8   | 1   | 39V51001 | O-RING, (6mm x 1.5)                         | X          |
| 10  | N/A | P3037020 | 1/8 TUBE - M3 CONNECTOR                     |            |
| N/A | N/A | 62504000 | KIT, REPAIR                                 | NOTED      |
| N/A | N/A | ISS003   | INSTRUCTION SHEET                           |            |

|                   |  |   |
|-------------------|--|---|
| <b>PARTS LIST</b> | <br><b>VEKTEK</b><br>VEKTEK, INC.<br>1334 E. SIXTH AVE. P.O. BOX 625<br>EMPORIA, KS. 66801 U.S.A. |   |
|                   | ASSEMBLIES AFFECTED<br>50-4085-00  | PARTS LIST, ASSY, SENSOR, POSITION, PNEU, OCO |
| DATE: 11/03/15    | DRAWING STATUS: <b>Released</b><br>PRODUCTION APPROVED FOR RELEASED STATUS ONLY  | SIZE<br>A <b>PL5003</b>                       |

|     |                        |                |            |         |
|-----|------------------------|----------------|------------|---------|
| E   | 5164                   | RELEASE        | RLK        | 8/28/23 |
| REV | IN ACCORDANCE WITH ECN | EFFECTIVE DATE | REVISED BY | DATE    |

SHEET 2 OF 2