



VEKTEK, INC.
1334 E. SIXTH AVE.
P.O. BOX 625
EMPORIA, KS. 66801
U.S.A

PARTS LIST

PL-7085

REV N
ECN 2503


ASSEMBLIES AFFECTED: 15-2718-00
15-2718-00F

DRAWN/DATE
ROMINE
09/29/00

ASSY, SC, LP, BF, 5000, SA, RH

UNIT WITH PLUNGER CLUTCH MODELS THAT APPLY

15-2718-00 , Revision D & Earlier
15-2718-00F , Revision D & Earlier



* INCLUDED IN SEAL KIT No. (Std.) 60-7110-09
(Fluorocarbon) 6V-7110-09

** INCLUDED IN SPRING KIT No. 61-7040-03

APPLY LUBRICANT TO ALL SEALS PRIOR
TO INSTALLATION

ALSO AVAILABLE:
IS-1505-INSTRUCTION SHEET


ASSY, SC, LP, BF, 5000, SA, RH

UNIT WITHOUT PLUNGER CLUTCH

AS OF 11/09/04

MODELS THAT APPLY

15-2718-00 , Revision E & Later
15-2718-00F , Revision E & Later



* INCLUDED IN SEAL KIT No. (Std.) 60-7110-09
(Fluorocarbon) 6V-7110-09

** INCLUDED IN SPRING KIT No. 61-7040-08

APPLY LUBRICANT TO ALL SEALS
PRIOR TO INSTALLATION

ALSO AVAILABLE:
IS-1505-INSTRUCTION SHEET

