



VEKTEK, INC.
1334 E. SIXTH AVE.
P.O. BOX 625
EMPORIA, KS. 66801
U.S.A.

PARTS LIST

PL-7087
REV N
ECN 2503

ASSEMBLIES AFFECTED:


15-2718-02
15-2718-02F

DRAWN/DATE

ROMINE
09/29/00

ASSY, SC, LP, BF, 5000, SA, STR

UNIT WITH PLUNGER CLUTCH
MODELS THAT APPLY
15-2718-02, Revision E & Earlier
15-2718-02F, Revision E & Earlier




* INCLUDED IN SEAL KIT No. (Std.) 60-7110-09
(Fluorocarbon) 6V-7110-09
** INCLUDED IN SPRING KIT No. 61-7040-03

ALSO AVAILABLE:
IS-1505 INSTRUCTION SHEET.

APPLY LUBRICANT TO ALL SEALS
PRIOR TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.

ASSY, SC, LP, BF, 5000, SA, STR

UNIT WITHOUT PLUNGER CLUTCH
AS OF 11/09/04
MODELS THAT APPLY
15-2718-02, Revision F & Later
15-2718-02F, Revision F & Later



ALSO AVAILABLE:
IS-1505 INSTRUCTION SHEET.
APPLY LUBRICANT TO ALL SEALS
PRIOR TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.
* INCLUDED IN SEAL KIT No. (Std.) 60-7110-09
(Fluorocarbon) 6V-7110-09
** INCLUDED IN SPRING KIT No. 61-7040-08

