



VEKTEK, INC.
1334 E. SIXTH AVE.
P.O. BOX 625
EMPORIA, KS. 66801
U.S.A.


PARTS LIST

PL-7092

REV K
ECN 2503

ASSEMBLIES AFFECTED: 15-2121-01
15-2121-01F


DRAWN/DATE
ROMINE
06/18/01



ASSY, SC, LP, BF, 7500, SA, LH

UNIT WITH PLUNGER CLUTCH
MODELS THAT APPLY
15-2121-01 , Revision C & Earlier
15-2121-01F , Revision C & Earlier

* INCLUDED IN SEAL KIT (Std) No. 60-7110-21
(Fluorocarbon) 6V-7110-16
** INCLUDED IN SPRING KIT No. 61-7040-06
APPLY LUBRICANT TO ALL SEALS PRIOR
TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.
FOR PROPER ARM MOUNTING SEE IS-1505



ASSY, SC, LP, BF, 7500, SA, LH

UNIT WITHOUT PLUNGER CLUTCH
AS OF 11/09/04
MODELS THAT APPLY
15-2121-01 , Revision D & Later
15-2121-01F , Revision D & Later

* INCLUDED IN SEAL KIT (Std) No. 60-7110-21
(Fluorocarbon) 6V-7110-16
** INCLUDED IN SPRING KIT No. 61-7040-09
APPLY LUBRICANT TO ALL SEALS PRIOR
TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.
FOR PROPER ARM MOUNTING SEE IS-1505

