



VEKTEK, INC.
1334 E. SIXTH AVE.
P.O. BOX 625
EMPORIA, KS. 66801
U.S.A

PARTS LIST

PL-7109

REV L
ECN 2503

ASSEMBLIES AFFECTED:


15212102
15212102F

DRAWN/DATE

ROMINE
05/23/02

ASSY, SC, LP, BF, 7500, SA, STR

UNIT WITH PLUNGER CLUTCH
MODELS THAT APPLY
15212102, Revision C & Earlier
15212102F, Revision C & Earlier




* INCLUDED IN SEAL KIT (Std) No. 60-7110-21
(Fluorocarbon) 6V-7110-16
** INCLUDED IN SPRING KIT No. 61-7040-06

APPLY LUBRICANT TO ALL SEALS PRIOR
TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.
FOR PROPER ARM MOUNTING SEE IS-1505

ASSY, SC, LP, BF, 7500, SA, STR

UNIT WITHOUT PLUNGER CLUTCH
AS OF 11/09/04
MODELS THAT APPLY
15212102, Revision D & Later
15212102F, Revision D & Later



* INCLUDED IN SEAL KIT (Std) No. 60-7110-21
(Fluorocarbon) 6V-7110-16
** INCLUDED IN SPRING KIT No. 61-7040-09

APPLY LUBRICANT TO ALL SEALS PRIOR
TO INSTALLATION
DO NOT USE SILICONE TYPE LUBRICANTS.
FOR PROPER ARM MOUNTING SEE IS-1505

